

Through connectors with heat shrink insulation 0.5 - 6 mm²

■ Data: Cu 99.95%, tin plated, heat shrink sleeve with melting glue inside.



	mm ²	Cat. no.	mm d	L	s	Pcs/pack	Rec. tool	Insulation
■	0,5-1,5	A1535SKW	4,5	35	8	25	GSW0560C	PA
■	1,5-2,5	A2535SKW	5,4	35	8	25	GSW0560C	PA
■	4-6	A4650SKW	6,8	40	9	25	GSW0560C	PA

s = strip length

After crimping and hot air gun heating, a water proof connection, glued to the cable and the connector, is achieved.

Parallel connectors 0.5 - 6 mm²

■ Data: Cu 99.95%, tin plated.

■ Insulation sleeves are halogen free.



	mm ² Total	Cat. no.	mm d	L	s	Pcs/pack	Rec. tool	Insulation
■	0,5-1,5	A1515PSK	3,2	17,0	7	100	GSA0760	PA
■	1,5-2,5	A2517PSK	4	17,0	8	100	GSA0760	PA
■	4-6	A4634PSK	5,6	21	9	100	GSA0760	PA

s = strip length

Type PSK must be crimped with GSA0760 (C) and with two crimps.

For detailed information regarding recommended tool, see tool section at the end of this chapter.